

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JAN 10 1 03 PM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

3a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-6859

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER -	7. Unit Agreement Name
2. Name of Operator Marathon Oil Company	8. Farm or Lease Name State E-6859-A
3. Address of Operator P. O. Box 220, Hobbs, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER P 990 FEET FROM THE South LINE AND 900 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 9S RANGE 36E NMPM.	10. Field and Pool, or Wildcat Allison-Penn
15. Elevation (Show whether DF, RT, GR, etc.) DF 4062'	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 20 sack cement plug at 7200'. Cut off 5-1/2" casing at 4600'. Placed a 25 sack cement plug in and out of the cut off 5-1/2" casing. Placed a 40 sack cement plug across the 9-5/8" shoe at 4182'. Cut the 9-5/8" casing off at 320'. Placed a 50 sack cement plug across the stub of the 9-5/8" casing at 320'. Placed a 10 sack cement plug in the 16" casing at the surface. The hole was filled with mud. A steel marker was installed per NMOC specifications. The well plugged and abandoned 12-30-66.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Area Supt. DATE 1-6-67

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: