| Form 9-331 a (Feb. 1961) PPROVER AUG 21 - 200 AUG 200 | (<i>SUBMIT IN T</i> UNITED S DEPARTMENT OF GEOLÓGICAI | STATES THE INTERIOR SURVEY | Budget Bureau No. 42-R358. Form Approved. Land Office Santa Fe Losse No. LC 067761 Unit |
|--|---|---|---|
| NOTICE OF INTENTION TO DRILL. NOTICE OF INTENTION TO CHANGE PLAN NOTICE OF INTENTION TO TEST WATER NOTICE OF INTENTION TO RE-DRILL OR NOTICE OF INTENTION TO SHOOT OR AC NOTICE OF INTENTION TO PULL OR ALC NOTICE OF INTENTION TO ABANDON WE | NS | BSEQUENT REPORT OF SHOO BSEQUENT REPORT OF ALTE BSEQUENT REPORT OF RE-D BSEQUENT REPORT OF ABAN PPLEMENTARY WELL HISTOF | ER SHUT-OFF DTING OR ACIDIZING ERING CASING PRILLING OR REPAIR NDONMENT RY |
| Well No | ABOVE BY CHECK MARK NATURE 660 ft. from $\begin{bmatrix} N \\ 3 \end{bmatrix}$ T 9 S R 36 E (Twp.) (Range) | of REPORT, NOTICE, OR OTH line and | From $\left\{ \begin{array}{c} \mathbf{E} \\ \mathbf{W} \end{array} \right\}$ line of sec. 11 |
| Allison Penn (Field) | Lea Count (County or Subdivis | У | New Mexico (State or Territory) |

DETAILS OF WORK

| (State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cem ing points, and all other important proposed work) | nent- |
|--|-------|
|--|-------|

Pull rods and tubing. Set permanent WL bridge plug at 9675 put 5 sacks cement on top of bridge plug. Perf abo formation from 9036 to 9053. Run tubing with hookwall packer and acidize with 1500 gallons N E Acid. Swab and test zone. If commercial production is not obtained plug perf. with 25 sacks cement, pull tubing, setting another 15 sacks cement plug at 4050 and put 10 sacks plug at surface with regulation marker. Fill with mud, laden, fluid between all plugs, no attempt will be made to pull any pipe from well

| nd that this plan of work must receive approval in writin | g by the Geological Survey before operations may be commenced. |
|---|--|
| <u> </u> | |
| Hobbs, N.M. | By Ofladeriner |
| | Title Disr ENGR |