

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. INFORMATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Idemeter Oil Company	8. LAND ACQUISITION Idemeter Federal
3. ADDRESS Box 149, Hobbs, New Mexico	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 FWL and 1830 FSL	10. WELLED, UNWELLED, OR WILDCAT WELLED
14. PERMIT NO.	15. ELEVATION (Whether DF, RT, GR, etc.) both GR
	11. SEC., T., R., M., OR BLK. AND SECTY Sec. 14, T9S, R36E
	12. COUNTY OR PARISH Deer STATE New Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Shot 2-7/8" tubing at 9482' and pulled up in 5-1/2" casing and set at 9475'. Laid 50 sack cement plug back to 9016'. Plug did not hold. Spotted another 25 sack plug but did not hold. Pumped in 100# of cotton seed hulls. Spotted 25 sacks cement at 9500', loaded hole. Top of plug at 9245'. Shot 5-1/2" casing off at 6012'. Pulled 5-1/2" casing. Set tubing at 6045'. Laid 25 sack cement plug back to 5938'. Set tubing at 5538', spotted 25 sack plug back to 5446'. Set tubing at 4280', spotted 25 sack cement plug back to 4194'. Set 10 sack cement plug in top and set marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

Original Signed By

C. L. WADE

TITLE

Area Supt.

DATE

6-8-66

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED DATE

NOV 1 1966

*See Instructions on Reverse Side

J. L. GORDON
ASST. CHIEF ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.