

**DUPLICATE**

COPY


Budget Bureau No. 42-R358.1.  
Approval expires 11-30-49.

(SUBMIT IN TRIPLICATE)

Land Office New Mexico

Lease No. 01616

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY



**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<b>X</b>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

\_\_\_\_\_, 19\_\_\_\_

**Federal Warren**  
Well No. 1 is located 660 ft. from N line and 660 ft. from E line of sec. \_\_\_\_\_

NW 1/4 NW 1/4 of Sec. 17 T-9-S R-36-E N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4097 ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The reason for plugging to abandon this newly drilled well, as discussed with Mr. M.H. Soyster, Engineer, is that no evidence of oil was found in the formation to which the well had been projected. Salt water was encountered in the lower part of the well; and the limestone section expected to be productive failed to show any signs of porosity, staining, odor or fluorescence after recovering 100% of the core made through the entire section.

Jet shots were discharged opposite this section and when tested failed to produce the slightest evidence of the presence of oil or gas. Records of the shooting and the drill stem tests made have been filed previously.

See supplemental sheet.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Forest Oil Corporation

Address Box 3222

Odessa, Texas

By

Title District Production Supt.