

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Abandoned oil well		7. Unit Agreement Name
2. Name of Operator Tom R. Minihan		8. Farm or Lease Name Santa Fe "F"
3. Address of Operator P.O. Box 4364 Midland, Tx. 79704		9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>south</u> LINE AND <u>660</u> FEET FROM <u>SE SW</u> THE <u>east</u> LINE/SECTION <u>20</u> TOWNSHIP <u>9S</u> RANGE <u>36 E</u> NMPM.		10. Field and Pool, or WHdcat Crossroads - Penn
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU Service Unit - Install BOP
2. Drill out cement plugs inside 7 5/8" casing and 5 1/2" liner to 9580' (TD 9605') Bottom 5 1/2" liner @ 9591'. Will test squeezes with 1000# while drilling out cement plugs.
3. Log and reperforate 9595' - 9605'. Acidize with 750 gals. 15% acid. Swab and test perforations. If commercial will equip well to pump and submit necessary form for allowable.
4. Will commence rededial work after cleaning out and testing Santa Fe "D" #1.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Owner & Operator DATE 11/3/82

ORIGINAL SIGNED BY

APPROVED BY JERRY SEXTON TITLE _____ DATE _____

CONDITIONS OF APPROVAL

NOV 10 1982