

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Gulf Oil Corporation</b>	8. Farm or Lease Name <b>H. L. Vinson</b>
3. Address of Operator <b>P.O. Box 98; Andrews, Texas 79714</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>A</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>22</b> TOWNSHIP <b>9-8</b> RANGE <b>36-E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Crossroads (Penn)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4057' IF</b>	12. County <b>Lea</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐  
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to pull rods & tbgs. Load the hole w/mud laden fluid. Run Guiberson type "BL" Anchor Assembly, bull plugged and latch into pkr @ 9566'. Cap "BL" Assembly w/2 sx sd and 2 sx cement w/dump bailer. Move in csg pullers, cut off 7" csg @ maximum recoverable depth. (Temperature Survey indicated cement top @ 5760'). Pull 7" to bottom of 9 5/8" intermediate csg & spot 100' plug from 4244' to 4144'. 9 5/8" shoe is @ 4194'. Finish pulling 7" csg. Remove surface head & spot a 50' surface plug in 9 5/8" csg. Install permanent 4" marker, fill cellar & pits. Clean location. Plugging operations should commence in January, 1970.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]*

TITLE **Area Engineer**

DATE **12-4-69**

APPROVED BY *[Signature]*

TITLE **SUPERVISOR DISTRICT**

DATE **3 1969**

CONDITIONS OF APPROVAL, IF ANY: