

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. V-2188

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TXO Production Corp.	8. Farm or Lease Name Humble State "C"
3. Address of Operator 900 Wilco Building, Midland, TX 79701	9. Well No. #1 (Re-entry)
4. Location of Well UNIT LETTER J, 2310 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 11-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Gladiola Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3889'	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103

10-1-88

through Drilling.

10-17-88

10-18-88 12,281' TD. Ran OH logs. Wellex TD 12,266' by WLM.

10-18-88 12,281' TD. Rn OH logs, Wellex WL TD 12,266'. RU Howco to plug. Spot 50  
sxs cmt plug @ 12,274'. LD 34 jts DP. Spot 50 sxs cmt plug @ 11,186'. LD  
63 jts DP. Spot 50 sxs plug @ 9212'. LDDP. LD 96 jts DP. Spot 50 sxs  
through plug @ 6204'. LD 54 jts DP. Spot 50 sxs @ 4496', LD 45 jts DP. Spot 50  
sxs @ 3102'. LD 27 jts DP. Spot 50 sxs cmt @ 2287'. LD 72 jts DP. Set 10  
10-20-88 sxs cmt @ surf. RD & MO rig @ 6:00 p.m., 10/19/88. P&A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M.C. Hestley TITLE Engineering Aid DATE 11/9/88

APPROVED BY Wm. H. Hill TITLE Field Rep. DATE 10/17/91

CONDITIONS OF APPROVAL, IF ANY: