NG. OF CO TES RE-	EIVED	Free C 102
DISTRIBUTI		Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE		Effective 1-1-65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		E-9035
	SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT US	SUNDRY NOTICES AND REPORTS ON WELLS THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	$\boldsymbol{\mathcal{X}}$
1.		7. Unit Agreement Name
OIL WELL X	GAS OTHER-	
2. Name of Operator		9 5 7 7 7 7 1 7 7 7 7
		8. Farm or Lease Name
<u>Amini ()it</u> 3. Address of Opera	Corporation	Humble A State
3. Address of Opera	\checkmark	9. Well No.
	owers West Midland, Texas 79701	2
4. Location of Wel.		10. Field and Pool, or Wildca:
UNIT LETTER	I 2130 FEET FROM THEEASTLINE AND1980 FEET FROM	Inha Dawa
	, FEET FROM THELICISL LINE ANDTOU FEET FROM	Inbe-Penn
South		ΔΗΗΗΗΗΗΗΗΗΗ
THE DOULI	LINE, SECTION 26 TOWNSHIP 10 S RANGE 33 E NMPM.	$\boldsymbol{\lambda} = \boldsymbol{\lambda} = $
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
İIIIIIIII	<u>4198 GL</u>	Lea
16.	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	
	SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL		ALTERING CASING
TEMPORARILY ABAND	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X
PULL OR ALTER CASH	CHANGE PLANS CASING TEST AND CEMENT JQB	
	OTHER	لـــا
OTHER		
17. Describe Propos work) SEE RUL	ed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
11-19-71	Marrad in soming will'read the second second	
11-19-71	Moved in casing pulling unit. Spotted 30 sx plug @ 9720',	, and fill hole w/mud.
11-30-71	Weld 4 1/2" pull nipple on. Shot csg. @ 6480', work csg.	wouldn't come.
12-03-71	Shot csg. @ 6339', wouldn't come.	
12-04-71	Shot csg. @ 5500' then 4500'	
12-05-71	Pulled 4 1/2" csg., set 25 sx plug @ 4500' - 4 1/2" stub.	Set 50 sk plug @ 3993'.
12-06-71	Shot 8 5/8" csg. @ 1015', wouldn't come, shot @ 790'.	
12-07-71	Pulled 8 5/8" csg., set 50 sx plug @ 790'. Set 25 sk plug	
•• • -	in top of 12 2/01 and and in to 11	@ 341. Set 10 sx plug
	in top of 13 3/8" csg., and installed marker.	
18. I hereby certify t	at the information above is true and complete to the best of my knowledge and belief.	
. 1		
\prec	Kind to during	
SIGNED	Me Added TITLE Agent	DATE 1-5-72
C (
APPROVED BY	Mm N. Munun VIII	
77		WAIE
CONDITIONS	PROVAL LE ANY	
CONDITIONS F AP	PROVAL, IF ANY:	

REEEVED

FEB 17 1972 OIL CONSERVATION COMME HOBES, N. M.