

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
E-8447

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator A. F. Roberts, Jr.	8. Farm or Lease Name Gulf State
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, New Mexico	9. Well No. 3
4. Location of Well UNIT LETTER J 2130 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 18 TOWNSHIP 11 S RANGE 34 E NMPM.	10. Field and Pool, or Wildcat Inbe Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4206 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned 6/30/73 as follows:

**Set cast iron bridge plug at 9722 & capped with 5 sacks cement.
Cut & pulled 5½" casing from 4281.
Spotted 105 sacks from 3900 to 4300 to cover 8 5/8" casing shoe
at 4020 and 5 1/2" stub at 4281.
Cut & pulled 8 5/8" casing from 1245.
Spotted 65 sacks 1240 to 1132.
Spotted 75 sacks 483 to 369 across 13 3/8" shoe at 433.
10 sacks at surface with regulation marker.
9.0# mud between all plugs.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Wanda Hedges* TITLE agent DATE 9/20/73

APPROVED BY *Nathan E. Clegg* TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: