

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
MM 315	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator		8. Farm or Lease Name	
TEXAS PACIFIC OIL CO., INC.		J. P. Collier	
3. Address of Operator		9. Well No.	
P. O. Box 1069 - Hobbs, New Mexico 88240		2	
4. Location of Well		10. Field and Pool, or Wildcat	
UNIT LETTER B , 660 FEET FROM THE North LINE AND 2130 FEET FROM		North Bagley Penn	
THE East LINE, SECTION 10 TOWNSHIP 11-S RANGE 33-E NMPM.			
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
4262' GR		Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Run tubing to 7450'. Displaced hole w/mud. Spot 100 sack plug @ 7450'.
2. Cut 7" casing @ 4178, 3927, 3844, 3675, 3509 & 3300'.
3. Circulated w/fresh water. Could not free 7".
4. Shot pipe @ 3090, 2897, 2686, 2478 & 2248'. Could not free 7".
5. Shot pipe @ 2000' and pulled.
6. Ran tubing to 2044', displaced hole w/mud, spot 50 sack plug at cut off.
7. Pulled tubing to 1740' and spot 50 sack plug at top of salt.
8. Spot 20 sack plug in top, cut off head and anchors, installed dry hole marker.
9. Cleaning location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	Original Signed By Claude Aubert, Jr.	TITLE	Area Superintendent	DATE	6-6-73
APPROVED BY	John W. Runyan	TITLE	Geologist	DATE	
CONDITIONS OF APPROVAL, IF ANY:					