

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-90
7. Unit Agreement Name
8. Farm or Lease Name State A
9. Well No. 1
10. Field and Pool, or Wildcat North Bagley
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Charles B. Gillespie, Jr.

3. Address of Operator
P.O. Box 8, Midland, Tx 79701

4. Location of Well
UNIT LETTER **N** **1980** FEET FROM THE **West** LINE AND **660** FEET FROM
THE **South** LINE, SECTION **3** TOWNSHIP **11S** RANGE **33E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4271 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Perforations 9408-9418' will have 50 sx plug spotted across them
2. 25 Sx plug will be set at 7500'
3. 5-1/2" casing will be out and pulled from approximately 6500'
4. 50 sx plug will be set across 5 1/2" casing stub at approximately 6500'
5. 25 sx plug will be set at 6100'
6. 25 sx plug will be set at 4500'
7. 25 sx plug will be set at 3800' at base of 9-5/8" casing
8. Will attempt to pull 9-5/8" casing from approximately 2000' 100' PLUG ACROSS TOP OF SALT IS REQ
9. 50 sx plug will be set across 9-5/8" casing stub
10. 25 sx plug will be set at 345' (base of 13-3/8) and at top of 13-3/8 at surface 100' PLUG
11. 4" marker will be welded on top of cut off braden head 20 SX PLUG
12. Location will be leveled

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Charles B. Gillespie, Jr.</u>	TITLE <u>Owner</u>	DATE <u>5-4-76</u>
Orig. Signed by <u>Jerry Sexton</u>		
APPROVED BY <u>Walt L. Suggs</u>	TITLE <u></u>	DATE <u>MAY 6 1976</u>
CONDITIONS OF APPROVAL, IF ANY:		