

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI
(Other instruction on re-
verse side)Form approved.
Budget Bureau No. 42-B1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR J. C. BARNES OIL CO.	8. FARM OR LEASE NAME SOUTHERN NAT. GAS FED.
3. ADDRESS OF OPERATOR P.O. BOX-505, MIDLAND, TEXAS 79701	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 740171 & 5411/E Unit I	10. FIELD AND POOL, OR WILDCAT INBE (N. PENN.)
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 1, 11-S 33-E
15. PURCH. FROM PUBCO	12. COUNTY OR PARISH LEA
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4190' GL.	13. STATE NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PREP. TO PLUG & ABANDON ON OR ABOUT AUGUST 25, 1972:

1. PROPOSE TO SET A CIBP WITH 20' CEMENT AT 9000'.
2. PROPOSE TO SPOT A 25 SX CEMENT PLUG AT 4 1/2" CASING STUB AT 6000'.
3. PROPOSE TO SPOT A 25 SX CEMENT PLUG AT TOP OF GLORIETTA AT 5290'.
4. PROPOSE TO SPOT A 25 SX CEMENT PLUG AT 7 5/8" CASING SHOE AT 4000'.
5. PROPOSE TO SPOT A 25 SX CEMENT PLUG AT 7 5/8" CASING STUB AT 2000'.
6. PROPOSE TO SPOT A 25 SX CEMENT PLUG AT 10 3/4" CASING SHOE AT 1860'.
7. PROPOSE TO SPOT A 10 SX CEMENT PLUG AT SURFACE WITH MARKER.
8. HOLE WILL BE LOADED WITH MUD-LADEN FLUIDS.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE PRODUCTION ACCT.

DATE 8-17-72

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 21 1972

**OIL CONSERVATION COMM.
HOBBS, N. M.**