

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Aug 19 11 39 AM '65

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-9021

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Wm. Barnhill	8. Farm or Lease Name Union-State
3. Address of Operator P. O. Box 1354 - Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER D , 990 FEET FROM THE north LINE AND 990 FEET FROM THE west LINE, SECTION 12 TOWNSHIP 11-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3942' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

8/14/65 Drilled to TD of 11,910' - Dolomite

8/15/65 Plugged & abandoned well as follows:

25 sack plug at total depth (11,910')
25 sack plug at top Miss (11,263')
25 sack plug at top Bough C (9,705')
25 sack plug at top Wolfe (9,000' - samples)
25 sack plug at top Abo (7,740')
25 sack plug at top Tubb (7,000' - samples)
25 sack plug at top Glor (5,740')
25 sack plug in & out of 8-5/8" csg at 4296'
25 sack plug at stub of 8-5/8" csg at 1288'
25 sack plug at top Anhy (2,243')
25 sack plug in & out of 11-3/4" csg at 384'
10 sack plug at surface with well marker in place.

Pits have been filled, location has been cleared & leveled, and is ready for inspection

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm B Barnhill TITLE Operator DATE 8/18/65

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: