

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Delaware Apache Corporation		8. Farm or Lease Name Hileman Estate
3. Address of Operator P. O. Box 1772, Hobbs, New Mexico 88240		9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>S</u> LINE AND <u>660</u> FEET FROM THE <u>E</u> LINE, SECTION <u>24</u> TOWNSHIP <u>9-S</u> RANGE <u>34-E</u> NMPM.		10. Field and Pool, or Wildcat Jenkins Cisco
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set Bridge Plug at 9650', 35' cement on top of bridge plug.
2. 100' Plug at 4529'. Cut off 4½".
3. 100' Plug at 4250'.
4. Cut off 8-5/8" with 100' Plug at 1226'.
5. 100' Plug at 400'.
6. 10 sacks at surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Guy Zahn TITLE Agent DATE 7-14-72

APPROVED BY Nathan E. Clegg TITLE OIL & GAS INSPECTOR DATE DEC 11 1972

CONDITIONS OF APPROVAL, IF ANY: