| NO. OF COPIES RECEIVED | | Form C-103 |
|-------------------------|--|---|
| DISTRIBUTION | HORRS OFFICE O. A. | Supersedes Old C+102 and C+103 |
| SANTA FE | HOBBS OFFICE O.C. | Effective 1-1-65 |
| FILE | Are I II . man | |
| U.S.G.S. | Dec 1 11 50 MI "66 | 5a. Indicate Type of Lease |
| LAND OFFICE | | State 🗶 Fee |
| OPERATOR | | 5. State Oil & Gas Lease No. |
| | · | 0G-670 |
| | RY NOTICES AND REPORTS ON WELLS oposals to drill or to deepen or plug back to a different reservoir. 'Ion for permit'' (form C-101) for such proposals.) | |
| 1. OIL GAS WELL | OTHER- TA | 7. Unit Agreement Name |
| 2. Name of Operator | | 8; Farm or Lease Name |
| Coastal States Gas Pr | oducing Company (Formerly Shell Oil Company) | M FM "A" State |
| 3. Address of Operator | | 9. Well No. |
| P. O. Box 235, Midla | nd, Texas 79701 | 4 |
| 4. Location of Well | | 10. Field and Pool, or Wildcat |
| | 1980 FEET FROM THE SOUTH LINE AND 660 | Flying "M" |
| | ON 17 TOWNSHIP 9-S RANGE 33-E NI | |
| | 15. Elevation (Show whether DF, RT, CR, etc.) 4392 DF | 12. County Lea |
| ^{16.} Check | Appropriate Box To Indicate Nature of Notice, Report or | Other Data |
| | | ENT REPORT OF: |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | ALTERING CASING |
| TEMPORARILY ABANDON | | PLUG AND ABANDONMENT |
| PULL OR ALTER CASING | CHANGE PLANS CASING TEST AND CEMENT JOB OTHER Temporary Aban | donment |
| OTHER Re-enter and comp | | |
| well | | |
| | perations (Clearly state all pertinent details, and give pertinent dates, inclu | iding estimated date of starting any proposed |

Well was originally drilled to TD 9285' by Shell Oil Company and temporarily abandoned. Reference Shell's Form C-103 of 12-28-65. Coastal States assumed operating ownership of well from Shell effective 10-1-66.

Casing has been set in well as follows:

- 1. Set 11-3/4", 40# at 411' w/350 sx cement. Circulated.
- 2. Set 8-5/8", 24# and 32# at 3751' w/400 sx cement.

Re-entry procedure will be as follows:

- 1. Clean out to 4500' TD.
- 2. Run, set, and cement 800' of 5-1/2", 14#, J-55 liner w/250 sx of cement.
- 3. Log well. Perforate w/1 jet shot per foot from 4433-35'; 4438-41'; 4446-50'; 4458-62', and 4474-80'.
- 4. Acidize w/2000 gallons of acid.
- 5. Run 2-3/8" tubing and rods. Place well on pump.

This notice filed in accordance with telephone conversation this date between Mr. E. F. Engbrecht and Coastal's George Krueger.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| SIGNED Al Refactuard | TITLE Div. Prod. Supt. | November 30, 1966 |
|---------------------------------|------------------------|-------------------|
| | | |
| | TITLE | DATE |
| CONDITIONS OF APPROVAL, IF ANY: | | |