

COPIES RECEIVED	
TRIBUTION	
FE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
E-7332

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Tipperary Oil & Gas Corporation	8. Farm or Lease Name Sinclair State
3. Address of Operator Box 3179, Midland, TX 79702	9. Well No. 2
4. Location of Well UNIT LETTER <u>L</u> , <u>660</u> , FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>22</u> TOWNSHIP <u>11S</u> , RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat N. Bagley Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4278' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug and abandon as follows:

Spot 100 sx plug @ 7335' (point of casing collapse)
Cut and pull 4 1/2" csg from approx. 4000'. *2000 HOLE w/ MUD*
Spot 50 sx @ top of 4 1/2" csg. *1/2 in & 1/2 out of CUT POINT*
Spot 50 sx @ 7-5/8" csg @ 3750'. *3800-3700*
Cut 7-5/8" csg @ 1000'.
Spot 100' plug @ top of 7-5/8" csg. *1/2 in & 1/2 out of CUT POINT*
Spot 100' plug @ 10-3/4" shoe, 367'. *417-317*
Spot 10' plug at surface w/ regulation marker.
Clean and level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED William F. Webb TITLE Petroleum Engineer DATE 10-6-77

APPROVED BY _____ TITLE SUPPLY DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Expires 4/11/78