

OIL CONSERVATION DIVISION
P. O. BOX 2080
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-79

DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.C.	
LAND OFFICE	
OPERATOR	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPERFORATE, PLUG BACK TO A DIFFERENT RESERVOIR, OR TO APPLY FOR PERMITS UNDER C-101 FOR SUCH PROPOSALS.

ON WELL ☐ CAS WELL ☐ OTHER ☒

Re-entry

30. Indicate Type of Lease

State ☒

Fed ☐

3. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Form of Lease Name

New Mexico State ☒

9. Well No.

1-B

10. Field and Pool, or Wildcat

Inbe Permo Penn

12. County

Lea

15. Elevation (Show whether DF, RT, GR, etc.)

4198 GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

OTHER ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-31-89 Spot 30 sks Class "C" cmt W.O.C. and tag plug @ 7437
8-31-89 Circulate hole w/ mud
9-5-89 Spot 50 sks Class "C" cmt @ 5795 W.O.C. and tog plug @ 5760
9-6-89 Spot 50 sks Class "C" cmt @ 5760 T.O.C. @ 5510
9-6-89 Spot 35 sks Class "C" cmt @ 5000 T.O.C. @ 4000
9-6-89 Spot 45 sks Class "C" cmt @ 4050 W.O.C. and tag plug @ 3938
9-6-89 Spot 45 sks Class "C" cmt @ 700 W.O.C. and tag plug @ 595
9-7-89 Spot 85 sks Class "C" cmt @ 440 W.O.C. and tag plug @ 317
9-7-89 Spot 10 sks Class "C" cmt @ surf
9-7-89 Weld on 1/4" steel plate and dry hole marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

F. D. Harvey

Superintendent

DATE 9-12-89

OIL & GAS INSPECTOR

NOV 16 1989