

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

RECEIVED OFFICE D. C. C.
 NEW MEXICO OIL CONSERVATION COMMISSION '66
 JUL 1 11 27 AM '66

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. K-956 & K-5471 |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator W. K. Byrom | 8. Farm or Lease Name State B |
| 3. Address of Operator P. O. Box 147 - Hobbs, New Mexico 88240 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER <u>I</u> . <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>9</u> TOWNSHIP <u>10S</u> RANGE <u>36E</u> NMPM. | 10. Field and Pool, or Wildcat Undesignated |
| 15. Elevation (Show whether DF, RT, GR, etc.) 4017 G. L. | 12. County Lea |

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
 TEMPORARILY ABANDON ☐
 PULL OR ALTER CASING ☐
 OTHER ☐

PLUG AND ABANDON ☒
 CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
 COMMENCE DRILLING OPNS. ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER ☐
 ALTERING CASING ☐
 PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-29-66: Ran Free Point, found 4½" casing to be free at 1172. Filled 4½" casing with 10# brine water and mud, and spotted a 25 sack plug at 4989 to 4750. Shot casing of at 1172, pulled casing and placed a 25 sack plug at 1172 to cover stub. Pumped a 25 sack down at the base of the 8-5/8" casing (290') and a 15 sack plug and 4" marker in the top of the surface. As soon as the pits have dried the location will be cleaned and anchor removed.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. K. Byrom

TITLE Geologist

DATE 6-30-66

APPROVED BY

John W. Ramsey

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: