

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-193  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-9669

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name ---
2. Name of Operator KKA Corporation	8. Farm or Lease Name New Mexico "CC" St.
3. Address of Operator 405 Wall Towers East - Midland, Tx. 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>O</u> , <u>554</u> FEET FROM THE <u>South</u> LINE AND <u>1874</u> FEET FROM THE <u>East</u> LINE, SECTION <u>27</u> TOWNSHIP <u>10-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat Inbe Permo Pennsylvania
15. Elevation (Show whether Dr, RT, GR, etc.) 4203 DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.

- 9-17-73 Spotted 30 sk. cement plug @9650'. Filled hole w/ mud laden fluid.
- 9-18-73 Shot 4 1/2" csg. @5500', 5000', & 4500'.
- 9-19-73 Pulled 4 1/2" csg. & set 55 sk. (100') plug @4111'. (4 1/2" stub)
- 9-20-73 Shot 8-5/8" csg. @1028' & pulled csg. Set 75 sk. (100') plug @ 1028'. (8-5/8" stub) Spotted 75 sk. (100') plug at base of surface csg. @350'.
- 9-21-73 Spotted 10 sk. plug @ surface. Set dry hole marker & cleaned location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nathan E. Keagy TITLE Agent DATE 10-8-73

APPROVED BY Nathan E. Keagy TITLE OIL & GAS COMMISSIONER DATE 10-8-73

CONDITIONS OF APPROVAL, IF ANY: