DISTRIBUTION  ANTA FE  ILE  S.G.S.  AND OFFICE	HOBBS STATE D. C. C.	Form C-103 Supersedes Old
ANTA FE ILE .S.G.S. AND OFFICE	HOBES OF THE D. C. C.	Supersedes Old
ILE .S.G.S. AND OFFICE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
S.G.S. AND OFFICE		Effective 1-1-65
AND OFFICE	FEB   4     39 AM '67	
	יוס מא כנו יוטאי	5a. Indicate Type of Lease
		State Fee.
PERATOR		5. State Oil & Gas Lease No. <b>K-2604</b>
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
<b></b>	ICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
Name of Operator	OTHER-	8, Farm or Lease Name
United States Smelting Refining and Mining Company		Bagley-State
P. O. Box 1877, Midland, Texas 79701		9. Well No. <b>3</b>
Location of Well	1980 FEET FROM THE West LINE AND 660 FEET FR	BEG RELET
THELINE, SE	ECTION 16 TOWNSHIP 11-S RANGE 33-E NM	PM. (
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4283 GR	Lea
	ck Appropriate Box To Indicate Nature of Notice, Report or	Other Data
NOTICE OF	FINTENTION TO: SUBSEQUE	ENT REPORT OF:
FORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
L OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	TOO AND ABANDONIMENT
	OTHER	
OTHER		
	s 8 5/8" 24# and 32# J-55 ST&C casing. Set at 3 50 pozmix. Plug down 2:30 A.M. 2-3-67/ WOC 24°	
350 sacks 50-5		tested casing with
		tested casing with