

COPIES RECEIVED	
DISTRIBUTION	
DATE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
<b>E-7324</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator <b>Clar-Don Products Co.</b>		8. Farm or Lease Name <b>State</b>
3. Address of Operator <b>c/o Oil Reports &amp; Gas Services, Inc., Box 763, Hobbs, N.M. 88240</b>		9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>P</b> , <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE SECTION <b>14</b> TOWNSHIP <b>10 S</b> RANGE <b>33 E</b> NMPM.		10. Field and Pool, or Wildcat <b>Inbe Perno Penn</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4210 KB</b>		12. County <b>Lea</b>

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

### Propose to plug as follows:

Set cast iron bridge plug @ 9675 with 5 sacks cement.  
Cut & pull 5 1/2" casing at 4500 approx.  
Spot 100' plug across 5 1/2" casing stub.  
Spot 100' plug @ 4007.  
Cut & pull 8 5/8" from 1200'.  
Spot 100' plug across stub.  
Spot 100' plug across 13 3/8" shoe @ 410.  
10 sacks at surface with regulation marker.  
Mud between all plugs.

APPROVED AS NOTED 24  
JAN 10 1973  
OFFICE OF THE COMMISSIONER OF  
LAND AND NATURAL RESOURCES  
SANTA FE, N.M.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wesley H. Hall TITLE Agent DATE 11/5/73

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: