State of New Mexico Ener Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT

OIL CONSERVATION DIVISION

	6. State Oil & Gas Lease No.		
10 Old Santa Fe Trail, Room 206 Santa Fe, New Mexi∞ 87503	WELL API NO. 30-025-22066 5. Indicate Type of Lease STATE F		

P.O. Box 1980, Hobbs, NM 88240	P.O. Box 1980, Hobbs, NM 88240 310 Old Santa Fe Trail, Room 206		WELL API NO.
DISTRICT II Santa Fe. New Mexico 87503		30-025-22066	
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brizos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.
SUNDRYNOT	ICES AND REPORTS ON WEI	16	
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESER		OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well:		A CONTRACTOR OF THE PARTY.	
WELL X WELL	OTHER		Huber Collier
2. Name of Operator			8. Well No.
Tipperary Oil & 3. Address of Operator	Gas Corp.		9. Pool name or Wildcat
4		land TX 7970	1 North Bagley Ferme Penn
Unit Letter <u>K</u> : 198	O Feet From The South	Line and198	0 Feet From The West Line
Section 18	Township 11S R		NMPM Lea County
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.) 9 G.L.	
11. Check A	Appropriate Box to Indicate	Nature of Notice, Re	eport, or Other Data
NOTICE OF INT	ENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT X
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
5/2/96 MIRUSU			
5/3/96 Pulled rods. Pumped 270 sx cmt at 4525'.			
5/6/96 Tagged TOC at 3885'with tbg. Pulled tbg. Cut csg at 3500' and pulled 4 1/2" csg.			
5/7/96 Circ 200 bbls Mud. PUH to 3550'. Pumped 25 sx cmt plug from 3550' to 3423'. WOC and tagged TOC at 3430'. Pulled tubing.			
5/8/96 Pulled 700' of 8 5/8" csg. RIH with tbg to 758 FFS. Pumped			
40 sx cmt plug. WOC and tagged TOC at 620'. PUH to 363'.			
Pump 60 sx	cmt plug. WOC and	d tagged TOC a	at 230'. Pump 15
nlace marke	face plug. Cut off er via orders of la	WH and Weld C	on plate. Did not
prace marke	i via orders or re	maowner and e)CD •
I hereby certify that the information above is true as	and complete to the best of my knowledge and be	lief.	
SKINATURE JOHN	Souther T	πε Engineer	DATE 5/22/96
TYPEOR PRINT NAME W. Jeffi	rey Sparks		ТЕГЕРНОМЕ NO. 915 683-5203
(This space for State Use)	<i>l.</i>		NUL 19 1996
APPROVED BY Jack	Influ	TE	DATE
CONDITIONS OF APPROVAL IF ANY:	7/		
₹			