|   | UIL CONSERVATION DIVISION                                | -                              |
|---|--|--------------------------------|
| DISTRIBUTION  |  | <b>f 1 1 1 1</b>               |
| BANTA FE  | P. O. BOX 2088   | Form C-103<br>Revised 10-1-7   |
| FILE  | SANTA FE, NEW MEXICO 87501                               |                                |
| U.S.G.S.  | 4  | 5a. Indicate Type of Lease     |
| LAND OFFICE   | 1  | State X Foe                    |
| OPERATOR  |  | 5. State OL: 6 Gas Lease No.   |
|   | -  | K-3983                         |
| SUNDRY NOTICES AND REPORTS ON WELLS<br>(DO NOT USE THIS FORM FOR PROPOSALS TO DAILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.<br>USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) |  |                                |
|   | OTHER- · .   | 7. Unit Agreement Name         |
| me of Operator  |  | 8. Farm or Lease Name          |
| ight A. Tipton  | · .  | Nine Ranch                     |
| iress of Operator   |  | 9. Well No.                    |
| Oil Reports & Gas S   | ervices, Inc., Box 755, Hobbs, NM 88241                  | 10. Field and Pool, or Wildcat |
| HIT LETTER <u>C</u> 66  | 0 FEET FROM THE NORTH LINE AND 2130                      | Inbe Permo Penn                |
|   | n <u>22</u> township <u>10 S</u> range <u>33 E</u>       |                                |
| ······································  |  |                                |
|   | 15. Elevation (Show whether DF, RT, GR, etc.)<br>4201 GL | 12. County<br>Lea              |
| Check A   | Appropriate Box To Indicate Nature of Notice, Repor      |                                |
| NOTICE OF IN  |  | EQUENT REPORT OF:              |
| RM REMEDIAL WORK  | PLUG AND ABANDON REMEDIAL WORK                           | ALTERING CASING                |
| DRARILY ABANDON   | COMMENCE DRILLING OPHS.                                  | PLUG AND ABANDONMENT X         |
| DR ALTER CASING   | CHANGE PLANS CASING TEST AND CEMENT JOB                  |                                |
| ۲EA   | OTHER  |                                |

Well P&A 6/16/87. Well Plugged & Abandoned as follows: Loaded hole with gel mud. Cut & pulled 5½" csg from 4900 Set 30 sack plug 4850 to 4950 Tag top of plug at 4850 Set 35 sack plug across 8 5/8" casing shoe at 3940 Tag top of plug at 3900 Cut & pulled 8 5/8" casing from 890' Set 60 sack plug across 8 5/8" stub at 890 Tag top of plug at 840 Set 70 sack plug across 12 3/4" casing shoe at 360 Tag top of plug at 310 Set 10 sack plug at surface with regulation marker.

All work witnessed by representative of Oil Conservation Division Location is cleared & levelled and ready for inspection. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE Higent VEnny Velles OIL & GAS INSPECTOR - 9 1988 COND **3/6**F E R

