

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Southland Royalty Co.	8. Farm or Lease Name Epperson "A"
3. Address of Operator 1100 Wall Towers West, Midland, Texas 79701	9. Well No. /
4. Location of Well UNIT LETTER C 660 North 1980 FEET FROM THE LINE AND FEET FROM West 25 11-S 33-E THE LINE, SECTION TOWNSHIP RANGE NMPM.	10. Field and Pool, or Wildcat INBE (Permo-Penn)
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐  
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Pull rods & tubing.
2. Run CIBP and set @ 9550'. Cap with 35' cmt.
3. Circulate the hole with 10.0# mud.
4. Run free point and cut 5½" csg.
5. Spot 100' plug across csg. stub.
6. Spot 100' plug across 8 5/8" csg. shoe @ 4000'.
7. Free point and cut 8 5/8" csg.
8. Spot 100' plug across csg. stub.
9. Spot 100' plug @ top of salt @ 950'. Tag plug.
10. Spot 100' plug across 11 3/4" csg. shoe @ 375'.
11. Spot 20' plug @ surface.
12. Clean up location & install surface marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. Harvey Can

TITLE Asst. to Div. Prod. Mgr

DATE 3-28-80

APPROVED BY [Signature]  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE MAR 31 1980