· v	•		
HO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old C-102 and C-103
SANTAFE	NEW MEXICO OIL CONSE	RVATION COMMISSION	Effective 1-1-65
FILE			Sa. Indicate Type of Lease
U.S.G.S.	·		State Fee
LAND OFFICE			5. State Oil & Gas Lease No.
OPERATOR			K-2289
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "PAPPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
OIL GAS WELL WELL	OTHER. P&A Disposal Well	L	7. Unit Agreement Name
2. Name of Operator			B. Farm or Lease Name
New Mexico Salt Water Disposal Co., Inc.			GG
3. Address of Operator			9. Well No.
Box 566, Roswell, New Mexico 88201			I-3*
			10. Field and Pool, or Wildcat
4. Location of Well T 1080 Fact 1080			
UNIT LETTER J 1980 FEET FROM THE East LINE AND 1980 FEET FROM			
South Line, section 10 township 11S range 34E nmpm.			
15. Elevation (Show whether DF, RT, GR, etc.)			12. County
			Lea ////////
16. Check	Appropriate Box To Indicate N	ature of Notice, Report or C	Other Data
NOTICE OF INTENTION TO: SUBSEQUENT			NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK  COMMENCE DRILLING OPNS.  CASING TEST AND CEMENT JQB	ALTERING CASING X

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pulled 5600 feet casing from 5600 feet. Set bridging plug at 9745 feet with three (3) sacks cement on top. Spotted mud, 100 bbls, at 5617 feet. Spotted 35-sack cement at 5617'-5517'. Spotted 35-sack cement plug at 4237'-4137'. Spotted 35-sack cement plug at 2013'-

1913'. Put 10-sack plug in top of casing and set marker, after cleaning cellar.

PULL OR ALTER CASING