

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-9035
7. Unit Agreement Name -----
8. Farm or Lease Name Humble "A"
9. Well No. 1
10. Field and Pool, or Wildcat -----
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Read & Stevens, Inc. 3. Address of Operator P.O. Box 2126, Roswell, New Mexico 88201 4. Location of Well UNIT LETTER A, 660 FEET FROM THE North LINE AND 810 FEET FROM THE East LINE, SECTION 26 TOWNSHIP 10 S RANGE 33 E NMPM.	15. Elevation (Show whether DF, RT, GR, etc.) 4194 GL
--	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

to set a bridge plug @ 9300' and set 2 sx of cement on top of plug.
to cut 5 1/2" csg @ 6000' and pull csg.
to set 35 sx plug @ 4488'-4600'
to set 50 sx plug @ 3827'-4000'
with good mud between plugs
to cut 8-5/8" csg @ 1039'
to set plugs with good mud between plugs.
to set 25 sx @ 1002' to 1054'
to set 25 sx @ 322' to 360'
to set 10 sx @ 10' to 0' and install Dry Hole Marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Joe D. Ramey</u>	TITLE <u>Agent</u>	DATE <u>1-10-72</u>
APPROVED BY <u>Joe D. Ramey</u>	TITLE <u>Dist. I, Supv.</u>	DATE <u>JAN 21 1972</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JAN 27 1972

OIL CONSERVATION COMM.
HOUSTON, TEX.