DISTRIBUTION  SANTA FE		ta.	
SANTA FE	現まらず。 第15章 5 <b>6. c. c.</b>		Form C-103 Supersedes Old
	NEW MEXICO OIL CONSERVATION COMMISSION AUG 11 1 32 14 67		C-102 and C-103
	NEW MEXICO DIL CONSE	HIC II II AA HEELA	Elffective 1-1-65
FILE		11 32 州 767	5a, Indicate Type of Lease
U.S.G.S.  LAND OFFICE		•	State Fee
OPERATOR			5. State Oil & Gas Lease No.
OPERATOR			0 = -4 =
SUMPE	Y NOTICES AND DEPORTS ON	WELL C	11111111111111111111111111111111111111
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIF.  USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)			
1.	TOR TOR TERMINE	- PROPOSES.	7. Unit Agreement Name
OIL GAS WELL	OTHER-		
2. Name of Operator			8. Farm or Lease Name
Charles B. Rea	d		Gross
3. Address of Operator			9. Well No.
P. O. Box 2126	Roswell, New Mexico	88201	2
4. Location of Well	TATOON COLO	7/50	10. Field and Pool, or Wildcat.
F	980 FEET FROM THE North	•	LUNDEDIGNATER
UNIT CETTER	FEET FROM THE	FEET FRO	
West	on 15 Township 10S	RANGE 33E NMPN	
THE LINE, SECTI	TOWNSHIP	RANGE NMPN	
	15. Elevation (Show whether I	DF, RT, GR, etc.)	12. County
	4193 GR		Lee
16. Check	Appropriate Box To Indicate N	ature of Notice Report of O	
	TENTION TO:	<del>-</del>	IT REPORT OF:
NOTICE OF I	TENTION TO.	308324321	THE ONE OF .
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORABILY ABANDON	1 200 AID ADAILS II	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	1 200 AND ASAMSON MENT
POLL OR ALIER CASING	CHANGE FEARS	OTHER	Γ-
		OTHER	
OTHER			
17. Describe Proposed or Completed O work) SEE RULE 1103.	perations (Clearly state all pertinent deta	ils, and give pertinent dates, including	g estimated date of starting any proposed
17. Describe Proposed or Completed O work) SEE RULE 1103.  Ran 295 jts (9, 6271) o shoe, insert float value Cemented with 250 sk	f 5½" csg 15.5# and 17# we, automatic fillup asses Incor-Pos-Mix A, 1% (Cested 1000# for 30 min)	set at 9640.21 KB, w/ mbly, 8 centralizers, CFR, 10# salt per sk.	Halliburton guide 10 scratchers. Plugged down
17. Describe Proposed or Completed O work) SEE RULE 1103.  Ran 295 jts (9, 627') o shoe, insert float value Cemented with 250 sk at 3:20 PM 8/3/67.  before perforating.	f $5\frac{1}{2}$ " csg 15.5# and 17# : ve, automatic fillup assessincor-Pos-Mix A, 1% (	set at 9640.21 KB, w/ombly, 8 centralizers, CFR, 10# salt per sk. no pressure drop, test	Halliburton guide 10 scratchers. Plugged down