

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG-584	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Charles B. Read		Skelly-State
3. Address of Operator		9. Well No.
P. O. Box 2126, Roswell, New Mexico 88201		2
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>F</u> <u>2086</u> FEET FROM THE <u>North</u> LINE AND <u>2086</u> FEET FROM		Vada (Undesignated)
THE <u>West</u> LINE, SECTION <u>10</u> TOWNSHIP <u>10S</u> RANGE <u>33E</u> N.M.P.M.		
11. Elevation (Show whether DF, RT, GR, etc.)		12. County
4229.8' GL		Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well in the following manner:

Hole filled with good mud.

Set plugs as follows:

25 sx plug @ 9500-9600'
25 sx plug @ 7500-7600'
25 sx plug @ 5192-5292'
25 sx plug @ 3863-3963'

Pulled 8 5/8" casing from 1502'

25 sx plug @ 1445-1545'
25 sx plug @ 340-440'
10 sx plug @ 0-10'
Installed regulation marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John W. Runyan TITLE Agent DATE 2/8/69

APPROVED BY John W. Runyan TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: