

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

3a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG-584	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - M (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole</u>		7. Unit Agreement Name
2. Name of Operator <u>Charles B. Read</u>		8. Farm or Lease Name <u>Skelly-State</u>
3. Address of Operator <u>P. O. Box 2126, Roswell, New Mexico 88201</u>		9. Well No. <u>2</u>
4. Location of Well UNIT LETTER <u>E</u> , <u>2086</u> FEET FROM THE <u>North</u> LINE AND <u>2086</u> FEET FROM THE <u>West</u> LINE, SECTION <u>10</u> TOWNSHIP <u>10S</u> RANGE <u>33E</u> N.M.P.M.		10. Field and Pool, or Wildcat <u>Vada (Undesignated)</u>
11. Elevation (Show whether DF, RT, GR, etc.) <u>4229.8' GL</u>		12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To set cement plugs as follows:

25 sx plug @ 9500-9600'
25 sx plug @ 7500-7600'
25 sx plug @ 5200-5300'
25 sx plug @ 3850-3950'

To cut and remove 8 5/8" casing

To set cement plugs as follows:

25 sx plug @ stub of 8 5/8" csg.
25 sx plug @ top of salt @ 2010'
25 sx plug @ 350-450'
10 sx plug @ 0-10'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 2/8/69

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: