

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

COPY

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
		5. State Oil & Gas Lease No. E-6468-5
OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
Name of Operator Amoco Oil Corporation		8. Farm or Lease Name Champlin State
Address of Operator 400 Wall Towers West Midland, Texas 79701		9. Well No. 1-Y
Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>810</u> FEET FROM THE <u>East</u> LINE, SECTION <u>26</u> TOWNSHIP <u>10 S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or Wildcat In the Permian Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4207 DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 11-22-71 Moved in casing pulling unit. Spotted a 60 sx cement plug @ 9770' and fill hole w/mud.
- 11-23-71 Weld 5 1/2" pull nipple on. Shot pipe @ 6494.
- 11-24-71 Pipe did not come shot @ 5981. Jack 4 jts. csg. out of hole.
- 11-26-71 Spot 25 sk plug @ 5981, pulled 650' of 5 1/2" csg., spot 25 sk plug @ 5350', pulled 1331' of 5 1/2" csg., spot 50 sk plug @ 3920'.
- 11-27-71 Shot 8 5/8" csg. @ 791', spot 25 sk plug @ 791' - 8 5/8" stub.
- 11-29-71 Spot 25 sk plug @ 3411. Set 10 sk plug in top of surface csg. and installed marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harold Godwin TITLE Agent DATE 12-23-71

APPROVED BY John W. Runyan TITLE Registrar DATE

CONDITIONS OF APPROVAL, IF ANY:

M