

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-6468-5

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Amini Oil Corporation 3. Address of Operator 400 Wall Towers West - Midland, Texas 79701 4. Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 810 FEET FROM THE East LINE, SECTION 26 TOWNSHIP 10-S RANGE 33-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4207' DF	7. Unit Agreement Name 8. Farm or Lease Name Champlin - State 9. Well No. 1-Y 10. Field and Pool, or Wildcat Vada Penn 12. County Lea
--	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

### Plugging Procedure:

- No. 1 Set 30 sk plug at 9770, and fill hole w/9.5 laden fluid, perf. @9791-9808'.
- No. 2 Top of cement behind 5½" casing @7000'.
- No. 3 Pull 5½" casing from 7000'.
- No. 4 Set 25 sk plug on top 5½" casing stub.
- No. 5 Set 25 sk plug @5350' on top of Glorieta.
- No. 6 Set 50 sk plug @3920' in bottom 8-5/8" csg.
- No. 7 Pull 8-5/8" casing from 1200', set 25 sk plug at stub.
- No. 8 Set 25 sk plug base of surface casing @341'.
- No. 9 Set 10 sk plug in top of 12-3/4" casing, set marker & clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Herin Godwin</u> Orig. Signed by Joe D. Ramey Dist. I, Supv.	TITLE <u>Agent</u>	DATE <u>10-21-71</u>
APPROVED BY _____	TITLE _____	DATE <u>OCT 26 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		