

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		5. State Oil & Gas Lease No.
2. Name of Operator Tom Brown Drilling Company, Inc.		7. Unit Agreement Name
3. Address of Operator P. O. Box 5706 Midland, Texas 79701		8. Farm or Lease Name L. C. Cooper et al
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 24 TOWNSHIP 9 S RANGE 32 E NMPM.		9. Well No. 1
10. Field and Pool, or Wildcat Flying M Penn South		
15. Elevation (Show whether DF, RT, GR, etc.) 4331 Gr.		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Set Whipstock to straighten old hole.	ALTERING CASING <input checked="" type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set cast iron bridge plug at 8950'. Dumped one sx cement on top of bridge plug. Cut casing off @ 6500'. Pulled 5-1/2" casing. Spotted first plug from 6500 to 6370 with 75 sxs. Spotted second plug from 6370 to 6188 with 85 sxs. Set Whipstock to straighten hole and to sidetrack 5-1/2" casing. Now drilling. Set whipstock at 6322'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm L Oliver TITLE Engineer DATE February 9, 1968

APPROVED BY J. L. Hance TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

See 1000 + 1000 + 1000 + 1000