

FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Roger C. Hanks		8. Farm or Lease Name Bridwell State
3. Address of Operator c/o Hobbs Pipe & Supply Co., P. O. Box 2010, Hobbs, N. M. 88240		9. Well No. 2
4. Location of Well UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>1</u> TOWNSHIP <u>9-S</u> RANGE <u>32-E</u> NMPM.		10. Field and Pool, or Wildcat Bar-U Penn
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was plugged and abandoned as follows:

1. Spotted a 30 sx cement plug 8,750'-8,950', plug did not hold.
2. Set bridge plug at 8,500' capped with 4' sx cement.
3. Loaded hole with mud-laden fluid.
4. Shot and pulled 4,165' 5-1/2" casing.
5. Spotted 35 sx cement plug across 5-1/2" casing stub at 4,165'.
6. Spotted a 40 sx cement plug across 8-5/8" casing shoe at 3,650'.
7. Shot and pulled 810' 8-5/8" casing.
8. Spotted a 35 sx cement plug across 8-5/8" casing stub at 810'.
9. Spotted a 50 sx cement plug across 11-3/4" casing shoe at 302'.
10. Spotted a 10 sx surface plug with marker.

Well was plugged and abandoned on December 1, 1973.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lynne Hammond TITLE Agent DATE 12/27/74

APPROVED BY Mr. W. Runyan TITLE Logist DATE _____

CONDITIONS OF APPROVAL, IF ANY: