

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG-498	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name -
2. Name of Operator Read & Stevens, Inc.		8. Farm or Lease Name Aztec
3. Address of Operator P.O. Box 2126, Roswell, New Mexico 88201		9. Well No. 2
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>2130</u> FEET FROM THE <u>West</u> LINE, SECTION <u>15</u> TOWNSHIP <u>10S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or Wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4205.7' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- Set CIBP on wire line @ 9490' w/4 sx. cmt. on top of plug.
- Loaded hole with heavy gel mud.
- Cut 5 1/2" csg. @ 4014', couldn't work free. Shot @ 3515', 3000' and csg. would not work free. Shot @ 2800', pulled and recovered 2800' of 5 1/2" csg.
- Spotted 50 sx. cmt. plug @ 2830' - 2700'
- Cut 8 5/8" csg. @ 1028', pulled and recovered 1028' of csg.
- Spotted cmt. plugs as follows:

1050' - 950'	65 sx.
400' - 300'	86 sx.
10' - 0'	10 sx.
- Installed dry hole marker.
- Will notify when location is ready for inspection.

13. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Nathan E. Vegg</u>	TITLE <u>Agent</u>	DATE <u>6/19/73</u>
APPROVED BY <u>Nathan E. Vegg</u>	TITLE <u>OIL & GAS</u>	DATE <u>JAN 1974</u>
CONDITIONS OF APPROVAL, IF ANY:		