

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-22218
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2427
7. Lease Name or Unit Agreement Name Maralo AKW State
8. Well No. 2
9. Pool name or Wildcat Vada Abo

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER RE-ENTRY	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>E</u> : <u>2130</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>16</u> Township <u>9S</u> Range <u>34E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4273' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-18-92. Dug around cellar. Made cut-off on 8-5/8" casing. RU BOP. WIH w/impression block. Tag up on cement. WIH w/7-7/8" bit. Drilled 35' with cement, metal, trash and wood. WIH w/impression block. No show. WIH w/7-7/8" bit, drill collars. Drilled to 99' with no show of 5 1/2" casing. Fell out at 118'. TIH and tagged up at 300'. Drill down to 1820'. Continued drilling. Drilled to 2162'. POH w/wash pipe. Had metal cuttings in circulation. Ran bit and resumed drilling on plug. Drilled out to 4018'. Circulated clean. No junk on top of cement. Displaced hole with mud. Drilled to 4065'. TIH. Tagged cement plug @ 4539'. Drilled and milled casing to 4557'. Circulated clean. TOH. TIH w/4-3/4" bit and 6 - 3-1/2" drill collars on 2-7/8" tubing. Tag top of 5-1/2" at 4557'. Drilled in 5-1/2" to 5636'. Circulated clean. POH. Laid down excess drill collars. TIH w/5-1/2" casing to 4557'. Latched onto 5-1/2" stub. RU wireline. Cemented w/250 sx Class "C" cement. WOC. Drilled out and tagged top of cement @ 4350'. Fell out of cement @ 4580'. Tagged cement @ 5640'. Drilling @ 5648'. WIH w/wash pipe and drilled to 5653'. Pull out with wash pipe shoe. Wore out. Went in w/4-3/4" bit. Tagged up @ 6623. Continued drilling @ 6687' in cement rock shale and metal.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 4-30-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 05 '92