

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-22228

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B9596

7. Lease Name or Unit Agreement Name

STATE MA

8. Well No.

3

9. Pool name or Wildcat

Moore Permo Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Amerada Hess Corporation

3. Address of Operator

P.O. Box 840, Seminole, Texas 79360

4. Well Location

Unit Letter M : 585 Feet From The SOUTH Line and 735 Feet From The WEST

Section 24

Township 11-S

Range 32-E

NMPM Lea

Count

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING

COMMENCE DRILLING OPNS. ☒

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set 3 1/2 C.I.B.P. @ 8330' Cap with 35' cement
- 2) Set 3 1/2 C.I.B.P. @ 8125' Cap with 35' cement
- 3) Set 2-7/8 C.I.B.P. @ 8125' Cap with 35' cement
- 4) Load 3 1/2 & 2-7/8 with mud
- 5) Set 3 1/2 C.I.B.P. @ 6000' Cap with 35' cement
- 6) Set 2-7/8 C.I.B.P. @ 6000' Cap with 35' cement
- 7) Spot 35 sacks cement Plug @ 2-7/8 & 3 1/2 Stub @ 3500' W.O.C. Tag plug @ 3375'
- 8) Load hole with mud
- 9) Perforate 8-5/8 casing @ 1510' Unable to pump into perforations Spot 55 sacks cement Plug @ 1556'
- 10) Spot 50 sacks cement & plug @ 733' W.O.C. Tag plug @ 594'
- 11) Spot 25 sacks cement Plug @ surface

Per Roy 10/5/95

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Raymond Maldonado

TITLE

Big Supervisor

DATE

10/24/95

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY

Jack Griffin

TITLE

ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

DATE

CONDITIONS OF APPROVAL, IF ANY: