

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-4601	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Southland Royalty Company		Shell State
3. Address of Operator		9. Well No.
1405 Wilco Building, Midland, Texas 79701		2
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER L, 1980 FEET FROM THE South LINE AND 440 FEET FROM		Inbe-Penn.
THE West LINE, SECTION 19 TOWNSHIP 11-S RANGE 34-E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4211.0' G.L.		Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-18-73 - Pull tubing and set CIBP at 9750' - spot 20' (2 sacks) cement on top of B.P.

1-20-73 - Casing Pullers, Inc., shot 5½" csg. at 4702'. Spot 35 sack cement plug from 4670-4750'. Pull 5½" csg. to 4060', spot 60 sack cement plug from 3870-4060', lay down csg.

1-23-73 - Shot 8 5/8" csg. at 1075' - laid down same. Ran tubing to 1116' - spotted 45 sack cement plug, pulled tubing to 355' - spotted 45 sack cement plug. Pulled tubing - spotted 10 sack plug in top of 11 3/4" csg. Installed dry hole marker.

WELL PLUGGED AND ABANDONED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Alton C. Goodrich TITLE Dist. Prod. Supt. DATE 2-28-73

APPROVED BY John W. Runyan TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: