

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b></p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL FORM C-101 FOR SUCH PROPOSALS.)</small></p>		<p>8a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>8. State Oil &amp; Gas Lease No. <b>30-7030</b></p>
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>2. Name of Operator <b>The Maurice L. Brown Company</b></p> <p>3. Address of Operator <b>Suite 200/Sutton Place Bldg./Wichita, Kansas 67202</b></p> <p>4. Location of Well UNIT LETTER <b>0</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1930</b> FEET FROM THE <b>East</b> LINE, SECTION <b>10</b> TOWNSHIP <b>10-3</b> RANGE <b>33-E</b></p>	<p>7. Unit Agreement Name</p> <p>8. Name of Lease Name <b>Skelly-State</b></p> <p>9. Well No. <b>2</b></p> <p>10. Field and Pool, or Wildcat <b>Vada Penn</b></p>	
<p>15. Elevation (Show whether DF, RT, GR, etc.) <b>4218' GR</b></p>	<p>16. County <b>Lea</b></p>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:      SUBSEQUENT REPORT OF:

<p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>PLUG AND ABANDON <input checked="" type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>
--	--	--	--

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig up PBCP Services, Inc.
2. Pull tubing and set cast iron bridge plug at 9538' (50' above 5½" casing perforations from 9588' to 9602'). \* 35' (min) cut on top C.I.B.P.
3. Displace hole with salt gel mud through tubing.
4. Spot 35 sacks cement through tubing at 5327' to form a 100' plug across top of Glorieta at 5297'.
5. Spot 35 sacks cement through tubing at 2550' inside 5½" casing to form a 100' plug across top of salt section est. at 2500' depth.
6. Spot 10 sacks cement at surface inside 5½" casing and erect dry hole marker.
7. Rig down PBCP Services, Inc.
8. Fill mud pit and cellar. Clean and level location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm. D. Dreesbeck TITLE District Engineer DATE 10-01-79

APPROVED BY John Runyan TITLE Engineer DATE OCT -4 1979

CONDITIONS OF APPROVAL, IF ANY:

\* note above