

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
**06-584**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Midwest Oil Corporation</b>	8. Farm or Lease Name <b>Skelly State</b>
3. Address of Operator <b>1500 Wilco Bldg, Midland, Texas 79701</b>	9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>0</b> <b>1980</b> FEET FROM THE <b>E</b> LINE AND <b>660</b> FEET FROM THE <b>S</b> LINE, SECTION <b>10</b> TOWNSHIP <b>105</b> RANGE <b>33E</b> NMPM.	10. Field and Pool, or Wildcat <b>Middle Lane (Pena)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4218.3 GL</b>	12. County <b>Lee</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was plugged & abandoned as follows:

1. C. I. B. P. set @ 9000' w/ 4sks cement on top of plug & loaded csg. w/mud.
2. Set 10 Sk. Cmt. plug @ surface & installed dry hole marker.  
(Note: 5 1/2" oil string was circulated w/cmt 10-27-67)  
Location cleaned & ready for final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gene Milford TITLE agent DATE 3/28/73  
Orig. Signed by  
John Runyan Geologist  
 APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE AUG 28 1975

CONDITIONS OF APPROVAL, IF ANY: