

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Vada "B" 673 Ltd.
9. Well No. 2
10. Field and Pool, or Wildcat Vada-Penn
12. County Lea

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator BTA Oil Producers
3. Address of Operator 104 South Pecos, Midland, Texas 79701
4. Location of Well UNIT LETTER "J", 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 20 TOWNSHIP 9-S RANGE 34-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4284 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

## Proposed Procedure:

Set CIBP @ 9750' w/2 sx cmt on top  
Cut & pull 4½" csg  
25 sx @ 4½" stub  
25 sx @ 5404' (Glorietta)  
25 sx @ 4010' (8-5/8" shoe)  
Cut & pull 8-5/8" csg  
25 sx @ 8-5/8" stub  
25 sx @ 370' (12-3/4" shoe)  
10 sx @ surface  
Install dry hole marker per NMOCC regulations

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>L. D. Boyce</u>	TITLE <u>Production Clerk</u>	DATE <u>9/17/71</u>
(If N. Signed by <u>Joe D. Ramsey</u> Dist. I, Supv.		
APPROVED BY _____	TITLE _____	DATE <u>SEP 30 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		