

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLE
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

M-2510

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

• • •

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Gonzales-Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Flying "C" (2A)
11. SEC., T., R., E., OR BLK. AND
SURVEY OR AREA

27, 9S, 33E

12. COUNTY OR PARISH

Lea

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection Well	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
3. Coastal States Gas Producing Company	9. WELL NO.
4. P. O. Box 235, Midland, Texas 79701	10. FIELD AND POOL, OR WILDCAT
5. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface	11. SEC., T., R., E., OR BLK. AND SURVEY OR AREA
6. 472.7' FWL & 1979' FSL, Unit L, Section 27, T-9-S, R-33-E, Lea County, New Mexico	12. COUNTY OR PARISH
14. PERMIT NO.	13. STATE
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	
4310.7 GR	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well No. 6 was plugged and abandoned 7-22-69 with 1093' of 4-1/2" casing recovered.
Plugs were set as follows:

1. Set cast iron bridge plug at 4424' with 2 sacks on top.
2. Set 30-sack plug at 1194-1094' (top of 4-1/2").
3. Set 30-sack plug at 338-238' (base of 8-5/8").
4. Set 10-sack plug at 13' to surface.
5. Installed dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED



TITLE

Division Production Manager

DATE

July 30, 1969

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

DATE

CONDITIONS OF APPROVAL, IF ANY:

OCT 16 1969

*See Instructions on Reverse Side

J L GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.