OISTRIBUTION SANTA FE FILE U.S.G.S. LAND OFFICE OPERATOR	NEW MEXICO OIL CONS	ERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 Sa. Indicate Type of Lease State X Fee 5. State Oil & Gas Lease No.
SUNDR	RY NOTICES AND REPORTS ON OPPOSALS TO DRILL OR TO DEEPEN OR PLUG BATTON FOR SUCTION FOR SU	WELLS	E-6387
1.	TOWN COLUMN COLOR SUCK	PROPOSALS.	7. Unit Agreement Name
2. Name of Operator	OTHER•		
Apache Corporation	ā		8, Farm or Lease Name Midwest State
3. Address of Operator			9. Well No.
c/o Hobbs Pipe & Su	pply Company, Box 201	lO, Hobbs, N. M.	3
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER E	1909 FEET FROM THE North	LINE AND FEET FRO	Inbe Permu Penn
THE West LINE, SECTI	ON 23 TOWNSHIP 10-S	RANGE 33-E NMPN	
	15. Elevation (Show whether i	DF, RT, GR, etc.)	12. County
	4314.7	7 G.L.	Lea
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	Appropriate Box To Indicate N NTENTION TO: PLUE AND ABANDON XX CHANGE PLANS	SUBSEQUEN PIEMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT QB	ALTERING CASING PLUG AND ABANDONMENT
 Describe Proposed or Completed O work; SEE RULE 1 103. 	perations (Clearly state all pertinent deta	ills, and give pertinent dates, including	g estimated date of starting any proposed
7 72 4 4	0.5	d ommit omeet	
	a 25 sx cement plug		s+ 2000!
· 2. Propose to spot	a 25 sx cement plug	at $5\frac{1}{2}$ casing stub	at 8000'.
2. Propose to spot 3. Propose to spot	a 25 sx cement plug a 25 sx cement plug	at $5\frac{1}{2}$ casing stub at top of Glorietts	a at 5307'.
2. Propose to spot 3. Propose to spot 4. Propose to spot 5. Propose to spot	a 25 sx cement plug a 25 sx cement plug a 25 sx cement plug a 25 sx cement plug a 25 sx cement plug	at $5\frac{1}{2}$ casing stub at top of Glorietts at 8-5/8 casing she at 8-5/8 casing sta	a at 5307'. be at 3920'. ub at 1700'.
2. Propose to spot 3. Propose to spot 4. Propose to spot 5. Propose to spot 6. Propose to spot	a 25 sx cement plug a 25 sx cement plug	at $5\frac{1}{2}$ casing stub at top of Glorietts at 8-5/8 casing she at 8-5/8 casing stat 11-3/4 casing states.	a at 5307'. De at 3920'. Ub at 1700'. Doe at 365'.
2. Propose to spot 3. Propose to spot 4. Propose to spot 5. Propose to spot 6. Propose to spot 7. Propose to spot	a 25 sx cement plug a 10 sx cement plug	at $5\frac{1}{2}$ casing stub at top of Glorietts at 8-5/8 casing shoat 8-5/8 casing stat 11-3/4 casing stat surface with mass	a at 5307'. De at 3920'. Ub at 1700'. Doe at 365'.
2. Propose to spot 3. Propose to spot 4. Propose to spot 5. Propose to spot 6. Propose to spot 7. Propose to spot	a 25 sx cement plug a 25 sx cement plug	at $5\frac{1}{2}$ casing stub at top of Glorietts at 8-5/8 casing shoat 8-5/8 casing stat 11-3/4 casing stat surface with mass	a at 5307'. De at 3920'. Ub at 1700'. Doe at 365'.
2. Propose to spot 3. Propose to spot 4. Propose to spot 5. Propose to spot 6. Propose to spot 7. Propose to spot	a 25 sx cement plug a 10 sx cement plug	at $5\frac{1}{2}$ casing stub at top of Glorietts at 8-5/8 casing shoat 8-5/8 casing stat 11-3/4 casing stat surface with mass	a at 5307'. De at 3920'. Ub at 1700'. Doe at 365'.
2. Propose to spot 3. Propose to spot 4. Propose to spot 5. Propose to spot 6. Propose to spot 7. Propose to spot	a 25 sx cement plug a 10 sx cement plug	at $5\frac{1}{2}$ casing stub at top of Glorietts at 8-5/8 casing shoat 8-5/8 casing stat 11-3/4 casing stat surface with mass	a at 5307'. De at 3920'. Ub at 1700'. Doe at 365'.
2. Propose to spot 3. Propose to spot 4. Propose to spot 5. Propose to spot 6. Propose to spot 7. Propose to spot	a 25 sx cement plug a 10 sx cement plug	at $5\frac{1}{2}$ casing stub at top of Glorietts at 8-5/8 casing shoat 8-5/8 casing stat 11-3/4 casing stat surface with mass	a at 5307'. De at 3920'. Ub at 1700'. Doe at 365'.
2. Propose to spot 3. Propose to spot 4. Propose to spot 5. Propose to spot 6. Propose to spot 7. Propose to spot	a 25 sx cement plug a 10 sx cement plug	at $5\frac{1}{2}$ casing stub at top of Glorietts at 8-5/8 casing shoat 8-5/8 casing stat 11-3/4 casing stat surface with mass	a at 5307'. De at 3920'. Ub at 1700'. Doe at 365'.
2. Propose to spot 3. Propose to spot 4. Propose to spot 5. Propose to spot 6. Propose to spot 7. Propose to spot	a 25 sx cement plug a 10 sx cement plug	at $5\frac{1}{2}$ casing stub at top of Glorietts at 8-5/8 casing shoat 8-5/8 casing stat 11-3/4 casing stat surface with mass	a at 5307'. De at 3920'. Ub at 1700'. Doe at 365'.

SIGNED STRICT STATE DATE 6/8/71

SUPERVISOR DISTRICT JUN 10 1971

CONDITIONS OF APPROVALLY

RECEIVED

JUN - 9 1971

OIL CONSERVATION COMM. HOBBS, N. M.