

N. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
L-6663

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Read & Stevens, Inc.	Inbe State
3. Address of Operator	9. Well No.
P. O. Box 2126, Roswell, New Mexico 88201	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER M 554 FEET FROM THE South LINE AND 554 FEET FROM	Inbe Permo Penn
THE West LINE, SECTION 24 TOWNSHIP 10S RANGE 33E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4203.6' GR	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well as follows on October 30, 1972:

1. Set 5-1/2" C.I. Bridge plug on tubing @9700'. Capped w/10 sacks of cement.
2. Loaded hole with good mud. Brine water and salt gel mixed. 4 bbls. to 1 sack.
3. Cut 5-1/2" casing @ 3987'. Pulled casing.
4. Set 35 sack cement plug @ 3999' to 3879'.
5. Cut 8-5/8" casing @ 1170'. Pulled casing.
6. Set 56 sack cement plug 1209' to 1098'.
7. Set 80 sack cement plug 410' to 310'.
8. Set 10 sack cement plug 10' to 0'.
9. Installed regulation dry hole marker.
10. Cleaned location.
11. Will notify when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John W. Remy TITLE Agent DATE October 30, 1972

APPROVED BY John W. Remy TITLE Agent DATE NOV 22 1972

CONDITIONS OF APPROVAL, IF ANY:

Dis...

RECEIVED

NOV 21 1972

OIL CONSERVATION ACT, 1971.
HQS, N. 10.