

| | | |
|------------------------|--|--|
| NO. OF COPIES RECEIVED | | |
| DISTRIBUTION | | |
| SANTA FE | | |
| FILE | | |
| U.S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. K 3983 |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Major, Giebel & Forster | 8. Farm or Lease Name Nine Ranch |
| 3. Address of Operator 1126 Vaughn Building, Midland, Texas 79701 | 9. Well No. 3 |
| 4. Location of Well UNIT LETTER K, 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 22 TOWNSHIP 10 S RANGE 33 E NMPM. | 10. Field and Pool, or Wildcat Inbe Permo Penn |
| 15. Elevation (Show whether DF, RT, GR, etc.) 4207 KB | 12. County Lea |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|--|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set cast iron bridge plug 20' above perforation: Perforation 9694-9705
2 sx cement on top of plug
25 sx cement @ stub of 5 1/2" casing
25 sx cement @ 5285' - Top Glorietta
40 sx cement @ shoe of 8 5/8" casing
25 sx cement @ stub of 8 5/8" casing
25 sx cement @ shoe of 12 3/4" casing
10 sx cement @ surface

Note: Add if not behind Pipe
25 sx cement top. Wolf.
25 " " Top A60
25 " " Top 3014
25 " " Base Salt

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| | | |
|-----------------------------------|-----------------|----------------------|
| SIGNED <i>Joe Guevara</i> | TITLE Engineer | DATE October 7, 1971 |
| APPROVED BY <i>John W. Runyan</i> | TITLE Geologist | DATE OCT 8 1971 |
| CONDITIONS OF APPROVAL, IF ANY: | | |

RECEIVED

DEC 10 1971

OIL CONSERVATION COMM.
WASHINGTON, D.C.