

csg then camera quit working – work camera loose, POOH, LD camera – Sent WL trk to Midland
for repair SWI & SDFN
DC: \$3,331 CC: \$66,839

3-1-2001

SD, wait on DH camera to be repaired – RU WL & run camera, RD WL, LD collars & pipe, ND
BOP, flanged up WH, RD, clean up location
DC: \$1050 CC: ~~\$67,889~~

#83,887 Corrected Total thru 3/31/2001 JIB