

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator BTA Oil Producers		8. Farm or Lease Name Max 677 Ltd.	
3. Address of Operator 104 South Pecos, Midland, Texas 79701		9. Well No. 1	
4. Location of Well UNIT LETTER "P" 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 30 TOWNSHIP 9-S RANGE 34-E NMPM.		10. Field and Pool, or Wildcat Vada-Penn	
15. Elevation (Show whether DF, RT, GR, etc.) 4284 GL, 4294 KB		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify NMOCC 24 hrs before operations commence.  
CIBP @ 9775' w/2 sx cmt on top  
Cut & pull 4½" csg T/C @ 8165'  
25 sx @ 4½" stub  
25 sx @ 5410' (Glorietta)  
25 sx @ 3988' (8-5/8" shoe)  
Cut & pull 8-5/8" csg  
25 sx @ 8-5/8" stub  
25 sx @ 375' (12-3/4" shoe)  
10 sx @ surface  
Install dry hole marker per NMOCC regulations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>L. D. Boyce</u>	TITLE <u>Production Clerk</u>	DATE <u>12/16/71</u>	
APPROVED BY <u>Joe D. Boyce</u>	TITLE <u>Dist. I, Supr.</u>	DATE <u>DEC 20 1971</u>	
CONDITIONS OF APPROVAL, IF ANY:			