

NO. OF COPIES RECEIVED
DISTRIBUTION
SANTA FE
FILE
U.S.G.S.
LAND OFFICE
OPERATOR

# NEW MEXICO OIL CONSERVATION COMMISSION

Form O-103  
Supersedes Old  
O-102 and O-103  
Effective 10-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
OG-5335

## SUNDRIY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM O-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
BTA Oil Producers	Lane "C" 674 Ltd.
3. Address of Operator	9. Well No.
104 South Pecos, Midland, Texas 79701	4
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER "C" 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 10-S RANGE 34-E NMPM.	Vada-Penn
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4262 GL	Lea

15.

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

### Plugging Procedure:

Set CIBP @ 9650' w/2 sx cmt on top  
Cut & pulled 4½" csg @ 5002'  
25 sx @ 5002'  
25 sx @ 3990 (8-5/8" shoe)  
Cut & pulled 8-5/8" csg @ 1200'  
25 sx @ 1200' (8-5/8" stub)  
25 sx @ 389' (13-3/8" shoe)  
10 sx @ surface  
Installed dry hole marker per NMOCC regulations  
Plugged & abandoned 9-21-71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. D. Boyce TITLE Production Clerk DATE 10/11/71

APPROVED BY Nathan E. Rezz TITLE \_\_\_\_\_ DATE 10/13  
CONDITIONS OF APPROVAL, IF ANY:

**RECEIVED**

**SEP 13 1971**

**OIL CONSERVATION COMM.  
HOBBS, N. M.**