

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG-5335	
7. Unit Agreement Name	
8. Farm or Lease Name	
Lane "C" 674 Ltd.	
9. Well No.	
4	
10. Field and Pool, or Wildcat	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator BTA Oil Producers	
3. Address of Operator 104 South Pecos, Midland, Texas 79701	
4. Location of Well UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>6</u> TOWNSHIP <u>10-S</u> RANGE <u>34-E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 4262 GL	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	SUBSEQUENT REPORT OF: PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed Plugging Procedure:

Set CIBP @ 9650' w/2 sx cmt on top
Cut & pull 4½" csg
25 sx @ 4½" stub
25 sx @ 5384 (Glorietta)
25 sx @ 3990 (8-5/8" shoe)
Cut & pull 8-5/8" csg
25 sx @ 8-5/8" stub
25 sx @ 389 (13-3/8" shoe)
10 sx @ surface
Install dry hole marker per NMOC regulations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>L. A. Boyce</u>	TITLE <u>Production Clerk</u>	DATE <u>9/3/71</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT I</u>	DATE <u>SEP 7 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

SEP - 7 1971

OIL CONSERVATION COMM.
HOBBS, N. M.