

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2789	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator R. R. Morrison		8. Farm or Lease Name Atlantic A St. Comm.
3. Address of Operator c/o John L. Cox, 408 West Wall, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>17</u> TOWNSHIP <u>10S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4232' GR		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Cut 2" tubing at 9445'. Pulled 9445' of 2" tubing.
2. Set 35-sack cement plug 9030-9445'.
3. Shot and cut 5-1/2" casing at 2450'. Pulled 2450' of 5-1/2" casing.
(6995' left in hole)
4. Set 25-sack cement plug 2350-2450'.
5. Shot and cut 8-5/8" casing at 1065'. Pulled 1065' of 8-5/8" casing.
(3035' left in hole)
6. Set 25-sack cement plug 1050-1150'.
7. Set 25-sack cement plug 350-450'.
8. Set 10-sack cement plug 0-10' with surface marker.
9. Plugging operations completed 8-25-71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gene House TITLE Prod. Clerk DATE 9-10-71

APPROVED BY William E. Clegg TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: