

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-3405	
7. Unit Agreement Name	
8. Farm or Lease Name	
State "18"	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Vada-Pennsylvanian	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	2. Name of Operator
	Champlin Petroleum Company
3. Address of Operator	
	300 Wilco Building, Midland, Texas 79701
4. Location of Well	
UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM	
THE <u>West</u> LINE, SECTION <u>18</u> TOWNSHIP <u>10-S</u> RANGE <u>34-E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
4213' DF	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was Plugged and Abandoned as follows:

4-29-77 Set CIBP @9500' w/50' of cement on top.
5-4-77 Shot 5-1/2" casing @2250' and pulled.
Set 50 sack plug 2250' to 2150'.
5-6-77 Shot 8-5/8" @1000' and pulled.
Set 100 sack plug from 1050' to 950'.
5-6-77 Set 150 sack plug from 443' to 220'.
5-9-77 Set 10 sacks in top of surface.
Installed Dry Hole Marker.
Hole loaded w/10# Mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter Mendelsohn TITLE District Clerk DATE May 27, 1977

APPROVED BY Eddie W. Leary TITLE OIL & GAS INSPECTOR DATE May 19 1977

CONDITIONS OF APPROVAL, IF ANY: